

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

AI185  
South  
1/4-1/2  
0.316 mi.  
1667 ft.  
VAULT #841  
W 12TH ST/SURF AVE  
BROOKLYN, NY  
Site 7 of 8 in cluster AI

NY Spills S103574534  
N/A

Relative:  
Higher

Actual:  
6 ft.

SPILLS:

Name: VAULT #841  
Address: W 12TH ST/SURF AVE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 9810539 / 2002-10-31  
Facility ID: 9810539  
Facility Type: ER  
DER Facility ID: 207199  
Site ID: 252937  
DEC Region: 2  
Spill Cause: Unknown  
Spill Class: C4  
SWIS: 2401  
Spill Date: 1998-11-19  
Investigator: JHOCONNE  
Referred To: Not reported  
Reported to Dept: 1998-11-19  
CID: 252  
Water Affected: Not reported

Spill Source: Commercial/Industrial  
Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 1998-11-19  
Spill Record Last Update: 2002-10-31  
Spiller Name: LISA PRIMEGGIA  
Spiller Company: VAULT #841  
Spiller Address: W 12TH ST/SURF AVE  
Spiller Company: 001  
Contact Name: LISA PRIMEGGIA  
DEC Memo:

"Prior to Sept, 2004 data translation this spill Lead\_DEC Field was  
O'CONNELL E2MIS NOTES 121387 11-19-98 17:00HRS V. VAVALLO REPORTS,  
FOUND 20 GAL OF UNKNOWN OIL ON 100 GAL OF WATER IN VS841 (7B53) HOLE  
IS CONTAINED & NO SEWERS OR WATERWAYS WERE AFFECTED. AT THIS TIME  
CANNOT DETERMINE INFO ON SEWER CONNECTION IN HOLE BECAUSE OF THE  
AMOUNT OF WATER. SPILL WAS DISCOVERED WHILE ATTEMPTING TO TAKE SAMPLE  
FROM T.M. UNIT CAN NOT BE PRESSURE TESTED UNTILL FEEDER IS GROUNDED.  
RECORD SHOWS 41PPM. 1 LIQUID SAMPLE TAKEN ON A 4-6HR TURNAROUND &  
ENV. STOP TAG # 06718 PLACED. ALSO S. ZALLOUGH I WAS NOTIFIED AT  
17:50HRS. 18:00HRS FLUSH IS ON ITS WAY TO LOC AT TO SET UP FOR  
CLEANUP UNTILL TANKER ARRIVES AT LOC. S.PACE 49874. UPDATE \*\*\*\* CIG  
WAS NOTIFIED AT 18:14HRS. S.PACE 49874. UPDATE\*\*\*\*\* EPA #  
NYP004029062 UPDATE\*\*\*\*\* 11-19-98 19:20HRS S. ZALLOUGH I  
REPORTS, BULLET PICKED UP SAMPLE AT 7:35PM (1 HOUR & 35MIN LATER.)  
FEEDER WAS GROUNDED AT 17:20 HRS & EQUIPMENT GROUP WILL GO FOWARD TO  
DETERMINE HOW MUCH FLUID WAS LOST. S.PACE 49874. UPDATE 11-19-98  
20:20HRS MR. WONG OF DEP HASMAT, PROFILED THE SPILL. HE WAS ADVISED  
BY WHITE HAT VITO VAVALLO THAT WE WOULD NOT BE ABLE TO DETERMINE HOW  
MUCH OIL WAS OUT OF TM UNTILL ALL GROUNDS & SAFETY MEASURES ARE TAKEN  
& WE EXPECT THAT TO HAPPEN APPROX 11PM. MR. K. KAVANAUGH ADVISED THAT

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

TANKER WILL ARRIVE BY 12:00HRS AND AT THAT TIME WE WOULD BE ABLE TO REMOVE FLUIDS & ADDRESS CLEANUP. FURTHER ARRANGEMENTS WERE MADE FOR REMOVAL OF TM IN THE MORNING. DEP ALSO REQUESTED SAMPLE , WHICH WAS GIVEN. HE ALSO REQUESTED A SAMPLE FROM T.M WHEN WE ARE ABLE TO DO CLEANUP, WILL SEND FIRST SAMPLE FROM THE CHEM LAB & WILL FAX TO DEP FAX # 595-4690.( ATTENTION MR. WONG.) HE ALSO WANTS COPY OF FIRST SAMPLE & SECOND SAMPLE FROM CHEM LAB FROM TM & WANTS THAT ONE FAXED ALSO. ADDITIONALLY WANTS FULL REPORT ON CLEANUP ACTIONS FROM COMPANY THAT S. ZALLOUGHY WOULD PROVIDE TO MR WONG AT 10:AM. WILL DRAIN TM AFTER FLUID IS REMOVED. S. PACE 49874. UPDATE\*\*\*\*\* 20:15HRS K. KAVANAUGH REPORTS, ASTORIA TRANSPORTION TANKER IS AVAILABLE AND BEING DISPATCHED NOW E.T.A AT 22:00HRS. S.PACE 49874.++++++22:30 11/19/98 VAVALLO #57666 O.S. EQUIPMENT GROUP LEAVING LOCATION CREW WILL STAY ON LOCATION.....22:34 K.KAVNAGH FLUSH FOREMAN REPORTED TANKER ON LOCATION CLEAN UP STARTING IN VS UPDATE 20-NOV-1998 00:55 FIRST SAMPLE RESULTS RECEIVED FROM CHEM LAB SEQUENCE #98-12830 RESULTS ARE 52 PPM \*\*\*\*\* \* UPDATE 20-NOV-1998 01:25 RESULTS OF FIRST SAMPLE FAXED TO MR.WONG ( DEP ) AS HE REQUESTED \*\*\*\*\* CAPPADONA \* UPDATE 20-NOV-1998 01:50 W. BOVE NETWORKS REPORTS HE TOOK A LIQUID SAMPLE ( OIL ) FROM TRANSFORMER \*\*\*\*HE WILL REQUEST A PRIORTY 4-6 HR TURNAROUND\*\*\* BULLET ORDERED TO DELIVER SAMPLE TO CHEM LAB \*\*\*\*\* WHEN RESULTS OF THIS SECOND SAMPLE ARE RECEIVED THEY ARE

ALSO TO BE FAXED TO MR.WONG ( DEP ) FAX # ( 718 ) 595-4690

\*\*\*\*\* CAPPADONA \*\*\*\*\* \* UPDATE

20-NOV-1998 02:32 O.S KAVANAGH FLUSH REPORTS UNIT HAS BEEN DRAINED AT THIS TIME \*\*\*\*\* CAPPADONA UPDATE 20-NOV-1998 04:00 W.BOVE REPORTS HE PRESSURE TESTED UNIT \*\*\*\* NOT HOLDING PRESSURE \*\*\*\*\* CAPPADONA UPDATE 20-NOV-1998 05:00 DELAROSA FLUSH REPORTS ALL LIQUIDS REMOVED & HOLE WASHED & CLEANED AS 50-499. UNIT TO BE REMOVED IN AM \*\*\*\* STOP TAG REMAINS IN PLACE UNTILL UNIT IS REMOVED & RESULTS OF SECOND SAMPLE ARE RECEIVED & HOLE TO BE DOUBLE WASHED 2ND LAB RESULT RECEIVED 11/20/98 - 0835. 98-12840. 36 PPM. TJ - 50495

\*\*\*\*\* 11/20/98 -

0911. 2ND LAB RESULT FAXED TO MR. WONG OF DEP. TJ - 50495

\*\*\*\*\* UPDATE:

11/20/98 - 1015 AS PER CONVERSATION WITH J. DEKANCHUK, STRUCTURE HAS NO CRACKS OR HOLES ON FLOOR OR WALLS. THERE IS A SUMP WITH NO DRAIN. UPDATE: 11/20/98 - 1030 S. ZALLOUGHY DISCUSSED THIS JOB WITH MR. WONG OF DEP. HE VALIDATED THAT THE LAB RESULTS WERE RECEIVED AND TOLD HIM OF THE FINDINGS ABOVE. MR. WONG EXPRESSED HIS SATISFATION WITH THE PROGRESS OF THE JOB. TJ - 50495 UPDATE: 11/20/98 - 1600 K. DEKANCHUK - O.S. - ENV. OPS., REPORTS UNIT WAS REMOVED AND THE 52 PPM CLEANUP IS COMPLETE AND TAG #06718 REMOVED. OVER 50 PPM CLEANUP PAPERWORK RETAINED WITH ENV. OPS. INCIDENT IS CLOSED. TJ - 50495"

"CON ED #121387 - SPILL DISCOVERED WHILE ATTEMPTING TO TAKE SAMPLE FROM TRANSFORMER IN VAULT-CLEAN UP CREWS ENROUTE."

Remarks:

All Materials:

Site ID: 252937  
Operable Unit ID: 1067763  
Operable Unit: 01  
Material ID: 569308  
Material Code: 0066A  
Material Name: unknown petroleum  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 20.00  
Units: G  
Recovered: .00  
Oxygenate: Not reported